

HUBBARD NINE DEPARTURE



DEPARTURE ROUTE DESCRIPTION

TAKEOFF RWY 31: Climb heading 314° to 1800 before turning left.

When entering controlled airspace, fly assigned heading and altitude, expect vector to appropriate route.

GREGG COUNTY TRANSITION (HUBB9.GGG): From over TTT VOR/DME on TTT R-094 to ROCKK INT, then on GGG R-279 to GGG VORTAC.

PARIS TRANSITION (HUBB9.PRX): From over TTT VOR/DME on TTT R-064 to ECKEY INT, then on PRX R-221 to PRX VOR/DME.

QUITMAN TRANSITION (HUBB9.UIM): From over TTT VOR/DME on TTT R-084 to SOLDO INT, then on UIM R-261 to UIM VOR/DME.

SOLDO TRANSITION (HUBB9.SOLDO): From over TTT VOR/DME on TTT R-084 to SOLDO INT.

TEXARKANA TRANSITION (HUBB9.TXK): From over TTT VOR/DME on TTT R-074 to SHERO INT, then on TXK R-244 to TXK VORTAC.

TYLER TRANSITION (HUBB9.TYR): From over TTT VOR/DME on TTT R-094 to ROCKK INT, then on TYR R-303 to TYR VOR/DME.

SC-2, 21 JUN 2018 to 19 JUL 2018

SC-2, 21 JUN 2018 to 19 JUL 2018